

Description of Repairs (invoice)	Labor	Time	Charges
REPLACE TIMIN BELR KIT	240	1	PARTS:
REPLACE IDLE AIR CTROL	60	1	\$ 390.79
			LABOR:
			\$ 300.00
			SUBLET/OTHER:
			\$ 0.00
			SUPPLIES:
			\$ 0.00
			FEES:
			\$ 0.00
			SUB-TOTAL:
			\$ 690.79
			TAX:
			\$ 48.36
**This charge represents costs and profits to the motor vehicle repair facility for miscellaneous shop supplies or waste disposal. ***FS403.718 mandates a \$1.00 fee for each new tire sold in the Sate of Florida. ***FS403.7185 mandates a \$1.50 fee for each new or remanufactured battery sold in the State of Florida.			<b>TOTAL:</b> <b>\$ 739.15</b>